

## **State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining**

MICHAEL R. STYLER Executive Director JOHN R. BAZA Division Director

## Inspection Report Minerals Regulatory Program

Supervisor

February 13, 2007

Mine Name: Rosebud Quarry	Permit number: M0030026 Inspection Date: May 4, 2006 Time: 10:00 am		
Operator Name: Star Stone Quarries, Inc.			
Inspector(s): Lynn Kunzler, DOGM			
Other Participants: Lon Thomas, Operator, Larry Garah	nana and Mike	Nielson, BLN	M
Mine Status: Active			
<b>Elements of Inspection</b>	Evaluated	Comment	Enforcement
<ol> <li>Permits, Revisions, Transfer, Bonds</li> <li>Public Safety (shafts, adits, trash, signs, highwalls)</li> <li>Protection of Drainages / Erosion Control</li> <li>Deleterious Material</li> <li>Roads (maintenance, surfacing, dust control, safety)</li> <li>Concurrent Reclamation</li> <li>Backfilling/Grading (trenches, pits, roads, highwalls,</li> <li>Soils</li> <li>Revegetation</li> </ol>			

**Purpose of Inspection:** 

This inspection was requested for an onsite pre-design of a proposed permit amendment.

**Inspection Summary:** 

1. This site was active during this inspection. The main purpose for this inspection was to determine what would be needed for a proposed amendment/revision to the approved Notice. In summary, Mr. Thomas summarized his proposed amendment/ revision as: he would like to culvert part of the ephemeral drainage and develop a waste dump on the south side. This would allow him to excavate the stone under the current waste dump and then systematically mine toward the northwest. Eventually he would be able to begin reclamation behind the advancing highwall. The Division and BLM then summarized regulatory requirements of what would need to be included, including new detailed maps, mining plan, reclamation plan, and details on culvert placement, sizing, and ultimate removal/reclamation. Given the scope of this project he was informed that it may be considered a revision to his Notice (significant change). BLM will also need to complete NEPA documents before this will be approved. Mr. Thomas was also informed that it would be at least late fall before it would be approved, pending on the completeness of his Notice.

It was also noted during this inspection that the white quarry to the northwest has been re-activated after several years of no activity.

## **Conclusions and Recommendations:**

Continue to monitor this site when in the area.

Inspector's Signature

LK:pb

O:\M003-BoxElder\M0030026-Rosebud\inspections\Insp-05042006.doc